

Hand Shower Kit

This exploded view diagram illustrates the components of a shower head assembly. The parts are numbered as follows:

- 1:** Curved shower arm with a hook.
- 2:** Black O-ring for the shower arm.
- 3:** Small cylindrical spacer.
- 4:** Small cylindrical spacer.
- 5:** Small cylindrical spacer.
- 6:** Large cylindrical spacer.
- 7:** Flat circular washer.
- 8:** Small cylindrical spacer.
- 9:** Small cylindrical spacer.
- 10:** T-shaped shower valve body.
- 11:** Small cylindrical spacer.
- 12:** Long, threaded shower arm.
- 13:** Small cylindrical spacer.
- 14:** Small cylindrical spacer.
- 15:** Small cylindrical spacer.
- 16:** Small cylindrical spacer.
- 17:** Main shower head body with a handle.
- 18:** Small cylindrical spacer.
- 19:** Shower head face with a perforated pattern.
- 20:** Flat circular washer for the shower head face.

The diagram shows the assembly sequence from the shower valve (10) through the various spacers (2-11, 13-16) and the main shower head body (17) to the shower head face (19) and its washer (20). A dashed line indicates the connection between the shower arm (1) and the main shower head body (17).